UNCLASSIFIED

AD NUMBER AD343602 **CLASSIFICATION CHANGES** TO: unclassified secret FROM: LIMITATION CHANGES TO: Approved for public release, distribution unlimited FROM: Distribution authorized to U.S. Gov't. agencies only; Foreign Government Information; 23 MAY 1963. Other requests shall be referred to The British Embassy,

AUTHORITY

3100 Massachusetts Avenue, NW, Washington,

DSTL, AVIA 18/4397, 20 May 2009; DSTL, AVIA 18/4397, 20 May 2009

DC 20008.

AD 343602L

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION
CAMERON STATION, ALEXANDRIA, VIRGINIA



SECRET

MOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

NOTICE:

THIS DOCUMENT CONTAINS INFORMATION

AFFECTING THE NATIONAL DEFENSE OF

THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18,

U.S.C., SECTIONS 793 and 794. THE

TRANSMISSION OR THE REVELATION OF
ITS CONTENTS IN ANY MANNER TO AN
UNAUTHORIZED PERSON IS PROBLETTED

EX LAW.

SEGRET No. AMERICANO.

st Part



1st Part of Report No. AAEE/890/10

MINISTRY OF AVIATION

AEROPLANE AND ARMAMENT EXPERIMENTAL ESTABLISHMENT

BOSCOMBE DOWN

HUNTER G.A. MK.11 WT. 810

CLEARANCE TRIALS OF 25 LB. PRACTICE BOMBING INSTALLATION

PRESENTED BY

ENG. LT. (A./O.) C. MOORE R.N. ARMAMENT DIVISION

1. THIS INFORMATION IS DISCLOSED FOR OFFICIAL THE RECIPIENT GOVERNMENT, EXCESSUAL TO ANY OTHER COVERNMENT OF RELEASE TO THE PRESS OR IN ANY OTHER WAY WOULD BE A BREACH OF THIS CONDITION.

2. THE INFORMATION SHOULD BE SAFEGUARDED UNDER RULES DESIGNED TO GIVE THE SAME STANDARD OF SECURITY AS THAT MAINTAINED BY HER MAJESTY'S GOVERNMENT IN THE UNITED KINDDOM.

3. THE INFORMATION CONTAINED IN THIS DOCUMENT SHOULD NOT BE CIRCULATED OUTSIDE GOVERNMENT DEPARTMENTS WITHOUT THE PRIOR PERMISSION OF THE MINISTRY OF AVIATION

4. THE PROGRAMS IS WARNED THAT HIS CONTAINED IN THE DOCUMENT MAY BE SUBJECT TO PRIVATELY - OWNED RIGHTS.

MINISTRY OF AVIATION

THE DOCUMENT IS THE PROPERTY OF MAL GOVERNMENT AND ATTENTION IS CALLED TO THE PENALTIES ATTACHING TO ANY INFRINGEMENT OF THE OPPICIAL SECRETS ACTS, 1911-1939

It is instanted for the sits of the recipions only, and for communication to each affacts using risks on may require to be expended with its contents in the course of that deste. The affacts constraint this power of communications or responsible that each information is imported with due content and receivers. Any power of the december, the character faithful report delaying postations of this december, the finding or externals, should forward it, together with its cause and address, in a classed excellent

THE SECRETARY. MINISTRY OF AVIATION, LONDON, W.C.2

Lotter parties need not be propole, other parties will be refunded. All parties are bandly married that the unsubstrated reseases or destruction of this decument is an offense against the Official



1963

AAEE Form I.

SECRETARIZATION DIN 5200.10

DOES NOT APPLY

1st Part of Report No. AAEE/890/10

ASROPLAND AND ARMAD AST. EXPORTMENT ESTABLISHMENT BOSCOMBE DOWN

23 MAY 1963

Hunter G.... Mk.11 -T.810

Clearance Trials of 25 lb. Practice Bombing Installation

Presented by

Eng. Lt. (A./O) C. Moore R.N. Armament Division

A. & A.E.E. Ref: ARM.M.14

AV/524/01 d. ted 18th June, 1962

M.O.A. Ref: Period of Trial: 4th October, 1962 to 23rd October, 1962

Summary

This Report gives details of the trials carried out to clear, for Service use, the 25 lb. Practice Bombing Installation fitted to Hunter G.A. Mk 11 aircraft.

It is recommended that this aircraft be cleared for carriage and release of 4 x 25 lb. Practice Bombs, with or without drop tanks on the outboard pylons, subject to the following:-

(a) Bomb Practice 25 lb. No.1 Nk.1

- (i) Carriage Speed not to exceed 500 knots I.A.S. (no restriction on I.H.N.)
- Speed not to exceed 500 knots I.A.S. Dive angle not to exceed 60°. (ii) Release

From store considerations, flight time at 500 knots I.A.S. should not NOTE: execued 30 mins. pur flight. After all flights, bombs not released must be carefully examined for presence of cracks and/or distortion of tail vanes before being cleared for further flights.

(b) Bomb Practice 25 lb. No.2 Mk.1

- Carriage Speed not to exceed 600 knots I.A.S. (no restriction on I.M.N.)
- (ii) Release Speeds up to the following:-

- 500 kts.I.A.S. With drop tanks on outboard pylons Without drop tanks on outboard pylons - 575 kts.I.A.S. Dive Angle - not to exceed 60.

- (c) Current aircraft limitations.
- (d) The recommendations contained in A. & A.E.E. letter, ref. ARM 87/11 dated 2nd January, 1963, concerning Electromagnetic Compatibility. (APPENDIZ I).

This Report is issued with the authority of

Air Commodore,

This document contains information affecting the National Commandint, A. & A.F.B. Defense of the Unity. The same in the seaming of the

..... Cecticum critical Sepi i de La da 100 **794.** At 1 to 1 to 2

in any manner to an unauthorized person is grapiblied

ME LOG."

The second secon

- 2 -

List of Contents

		Page
1.	Introduction	3
2.	Object of Trial	3
3.	Description of Installation	3
4.	Method of Trial	3
5.	Results of Trial	3
6.	Conclusions	4
7.	Recommendations	4

Mat of Appendices

	Appendix
Electromagnetic Compatibility Trials Report (A. & A.E.E. letter, ref. ARM 87/11 dated 2nd January,1963).	I

/1. Introduction ...

1. Introduction

- (a) In accordance with Ministry of Aviation Trials Proforma, Authority No. N.42, ref. AV/524/01 dated 18th June, 1962, trials to clear, for Service use, the 25 lb. Practice Bombing installation fitted to HUNTER G.A. Mk. 11 aircraft have been completed.
- (b) The trial commenced on 4th October, 1962 and was completed on 23rd October, 1962.
- (c) A clearance was recommended by A. & A.E.E. Signal No. AR. 178, dated 10th October, 1962, and an interim Report, reference ARM. M.14, was issued on 23rd October, 1962.

2. Object of Trial

The object of the trial was to clear the installation for carriage and release of 4 x 25 lb. Practice Bombs No.1 Mk.1 and No.2 Mk.1.

3. Description of the Installation

- (a) The installation is similar to that fitted to Hunter T. Mk.8 aircraft, which is fully described in AP(N) 1023 (12).
- (b) One 25 lb. Practice Bomb Carrier is fitted to each inboard pylon (Mod. 667) by means of a No.1 Mk.1 B.R.U.

4. Method of Trial

4.1 Ground Examination

The ground examination consisted of:-

- (a) Installation and removal of practice bomb carriers.
- (b) Loading and unloading drill stores.
- (c) Electromagnetic compatibility checks of the installation.

4.2 Flight Tests

Release flights were flown to check the functioning of the practice bomb release circuits.

5. Results of Trial

5.1 Ground Examination

- (a) Installation and removal of practice bomb carriers presented no difficulties.
- (b) Practice bombs can be loaded and unloaded without difficulty, using standard procedures.
- (c) Results of the Electromagnetic Compatibility checks are contained in A. & A.E.E. letter, ref. ARM 87/11, dated 2nd January, 1963. (APPENDIX I).
- (d) It was noted that the inboard pylons (Mod. 667) were labelled with a reference to "PRACTICE/NORMAL" switch positions. This switch has been deleted from the pylons; circuits are selected by operation of the "Fuze/Defuze" switch in the cockpit. This defect was reported on Form A.24 BD/RNC/214/0/62 dated 12th October, 1962.

/5.2 Might ...

5.2 Flight Tests

Three check release flights were flown. One flight was successful, one abortive due to fouling of the range and one partially successful due to a defective port practice bomb carrier.

6. Conclusions

It is concluded that the Hunter G.A. Mk.11 aircraft 25 lb. Practice Bombing installation can be cleared by analogy with the Hunter T. Mk.8 aircraft.

7. Recommendations

It is recommended that the Hunter G.A. Nk.11 aircraft be cleared for carriage and release of 4 x 25 lb. Practice Bombs, with or without drop tanks on the outboard pylons, subject to the following:-

(a) Bomb, Practice, 25 lb. No.1 Mk.1

- (i) <u>Carriage</u> Speed not to exceed 500 knots I.A.S. (no restriction on I.M.N.)
- (11) Release Speed not to exceed 500 knots I.A.S. Dive angle not to exceed 60°.

From store considerations flight time at 500 knots I.A.S. should not exceed 30 minutes per flight. After all flights, bombs not released must be carefully examined for presence of cracks and/or distortion of tail vanes before being cleared for further flights.

(b) Bomb, Practice, 25 lb. No.2 Mk.1

- (i) <u>Carriage</u> Speed not to exceed 600 knots I.A.S. (no restriction on I.h.N.).
- (ii) Release Speeds up to the following:-

With drop tanks on outboard pylons - 500 kts. I.A.S. Without drop tanks on outboard pylons - 575 kts. I.A.S. Dive Angle - not to exceed 60.

- (c) Current aircraft limitations.
- (d) The recommendations contained in A. & A.E.E. letter, ref ARM 87/11, dated 2nd January, 1963, concerning Electromagnetic Compatibility. (APPENDIX I).

Circulation List

D.A. Arm.	-	8 Copies 1 for Action
A.D. (R.A.F.)C.	-	2 Copies (for information of D.P.O.)
A.D.A.D.R.	***	1 Copy
A.D. S. & G.	-	1 Copy
A.D.P. An.	-	1 Copy
C.A.S.L.O.	-	1 Copy
R.D.T.3	-	1 Copy
T.I.L.	-	50 Copies
R.A.E.	-	6 Copies
R.A.E. Bedford	-	2 Copies
R.T.O. Hawkers	-	2 Copies

Appendix I to 1st Part of A. & A.E.E. Report No. <u>890/10</u>

Tel: Amesbury 3331

Ext: 300

Ministry of Aviation, Aeroplane and Armament Experimental Establishment, Boscombe Down, Salisbury,

Ref: Arm. 87/11

Armament Division

Wilts.

2nd January, 1963.

The Secretary, Ministry of Aviation, (A. Arm. 2), St. Giles Court, 1-13 St. Giles High Street, LONDON. W.C.2.

For the attention of Group Captain A. W. Eyre

Hunter G.A. Mk.11 - Electromagnetic Compatibility Trials Report

The report on the electromagnetic compatibility trials conducted on a Hunter G.A. Mk. 11 aircraft at A. & A.E.E. is forwarded herewith.

> Signed (C. R. C. HOWLETT) Group Captain

for Chief Superintendent, for Commandant,

> A. & A.E.E. Boscoabe Down.

External Distribution:

M.O.A. N.A./D.A. Arm. M.O.A. A. Arm. 1(a) N.O.A. R.A.F./C.1 N.O.A. A. Arm. 2(b) M.O.A. A. Arm. Plans Admiralty D.N.A.D. Admiralty D.G.A. Admiralty D. of S.

Secretary, Ordnance Board - Attn. Mr. Cousens

Director, R.A.E. - Attn. Mr. Corn (Teapons Dept.) W.E. 7 Director, R.A.E. - Attn. Mr. Green (Weapons Dept.) W.E. 4

Internal

0.C. 'C' Sqdn. Commandant T.W.G. Chief Superintendent Supt. of Engineering A.S. of A. Spares (4 copies) Supt. of Nav./Radio

SECRET

Hunter G.A. Nk.11 - Electromagnetic Compatibility - Report or Trials to determine the effect on the reliability and safety of the Weapon Systems

Appendices

A	Trials Programme - E.R.U.
В	Trials Programme - 2" R.P.
C	Trials Programme - 3" R.P.
D	Airborne Radio Installations and Electrically operated services.
E	Modification state of the aircraft.
F	Results - E.R.U.
G	Results - 2" R.P.
H	Results - 3" R.P.

INTRODUCTION

- 1. A trial was conducted at A. & A.E.E., Boscombe Down, between the 5th and 10th October, 1962, to establish the electromagnetic compatibility of the weapon systems with the aircraft installed electrical and radio equipment in respect of the Hunter G.A. Mk.11 aircraft. No flying trials were conducted.
- 2. Authority for this trial is given in M.O.A. Armament Trials Proforms, number N4O, dated 1st June, 1962.

TRIALS PROCEDURE

Object of Trial

3. The object of the trial was to investigate the electromagnetic compatibility of the weapon systems detailed in para. 5 with respect to the Hunter G.A. Mk.11 aircraft and to make recommendations to support a C.A. clearance.

Description of Equipment Under Test

- 4. The trial was carried out on a representative service aircraft, Munter G.A. Mk.11, WT.810. A list of the aircraft modifications, S.T.I.'s etc. is given at Appendix E.
- 5. Investigations were made into the following weapon systems:-
 - (a) E.R.U. (Jettison for 25 lb. bomb carrier, 2" rocket pod and overload fuel tank).
 - (b) 2 inch rocket weapon system.
 - (c) 3 inch rocket weapon system.

Description of Test Equipment

- 6. The instrumentation for the trial consisted of ferrite core detector type instruments to detect the surge and A.C. pick up, and diode voltmeter type instruments to measure the R.F. pick up.
- 7. The ferrite core detector type instrument and the box R.A.E. No.2 (diods voltmeter) were supplied by R.A.E., Farnborough, the latter being fully described in R.A.E. Report ARM 4611/A/GWH. The diode voltmeter BD/1 was built by A. & A.E.E., Boscombe Down.

Conduct of Trial

8. The aircraft was equipped in the three roles given in paragraph 5. An investigation was made in each role to ascertain the electromagnetic compatibility hazard from the aircraft installed electrical and radio equipments.

/9. ...

- 2 -

- 9. A list of the aircraft electrical equipments and airborne radios which were operated during the trial is given at Appendix D.
- 10. The detailed test programmes for the trial are attached as Appendices A, B and C.

RESULTS OF THE TRIAL

Ejector Release Unit

- 11. The maximum surge or A.C. pick up was not more than 1.2 volts for less than 0.5 micro second. The full results are given at Appendix F.
- 12. The maximum R.F. pick up was 3.6 milliwatts. The complete results are shown at Appendix F.

2 inch Rocket Battery

- 13. There was no indication of any surge or A.C. pick up on the 2" rocket system. The results are given in Appendix G.
- 14. The maximum amount of R.F. pick up was 1.05 milliwatts. Detailed results are given in Appendix G.

3 inch Rocket Projectile System

15. There was one indication of surge on this system. The amount of energy picked up was between 2.5 and 15 microjoules. Detailed results are given in Appendix H.

SAFETY ASPECTS OF CONDUCTING COMPOSITION CAPS

- 16. The Ejector Release Unit is a No.1 Mk.1 and is fitted in the inboard (Mod. 667) pylons. The E.R.U. cartridge is initiated by an 18 volt graphite cap which has a high sensitivity and a resistance tolerance of between 12 and 180 ohms.
- 17. It has been considered necessary on other aircraft armament installations (utilising conducting composition caps) to introduce a safety device into the electrical firing circuit. Such a safety device has been considered necessary because of the sensitivity of conducting composition caps which can fire at 5 volts D.C.
- 18. The device consists of a relay built into the connector which is attached to the cartridge cap such that both terminals of the cartridge are connected to earth until the firing pulse energises the relay, removes the earth connection and allows the pulse to fire the cap.
- 19. Modifications are already being incorporated by:-
 - (a) Frasher Nash on the No.2 Mk.1 E.R.U. 11A/4520 Modification Arm. 2869.
 - (b) M.L. Aviation on the No.3 Mk.2 E.R.U. 11A/5712.
- 20. It is considered that this form of protection to the E.R.U. firing circuit should be applied to the No.1 Mk.1 E.R.U. This will increase the confidence level that inadvertent operation due to induced R.F. and transient voltages will not occur, within the limitations of this method of attenuation.

- 3 -

CONCLUSIONS

- 21. It is concluded that:-
 - (a) The E.R.U. could, due to the high sensitivity of the 18 volt graphite cap, be hazarded by:-
 - (i) Surge or A.C. pick up from internal aircraft sources.
 - (ii) R.F. pick up from aircraft radio equipment.
 - (b) The 2" rocket battery and 3" rocket system picked up:-
 - (i) Surge from internal aircraft sources
 - (ii) R.F. from aircraft radio transmissions
 - at a level insufficient to constitute a hazard.

RECOMMENDATIONS

- 22. It is recommended that the Ejector Release Unit firing system fitted to the Hunter G.A. Mk.11 aircraft to the modification state listed in Appendix E and to the airborne radio installation state listed in Appendix D be given a clearance in respect of freedom from electromagnetic induction hazards to safety and reliability of functioning subject to the satisfactory incorporation of the attenuating device outlined in paragraphs 17 to 19.
- 23. It is recommended that the 2" and 3" rocket systems fitted to the Hunter G.A. Mk.11 aircraft to the modification state listed in Appendix E and to the airborne radio installation state listed in Appendix D be given a clearance in respect of freedom from electromagnetic induction hazards to safety and reliability of functioning.
- 24. It is further recommended that no aircraft radio installations shall be operated during the loading or unloading of:-
 - (a) E.R.U. cartridges.
 - (b) 2" Rockets.
 - (c) 3" Rockets.

Appendix A to Arm. 87/11dated 2nd January, 1963

Hunter G.A. Mk.11

Tests to Ascertain Electromagnetic Compatibility with Aircraft Meapon System

Jettison Facility - E.R.U.

1. Aircraft Circuit Checks

- (a) Ensure that all explosives have been removed from the aircraft and an entry made in F.700.
- (b) Connect and switch "ON" ground power supplies.
- (c) Fit Armament Safety Plug to the socket in the underside of the port mainplane.
- (d) Place the Butt Test switch to "ON".
- (e) Select the Fuzing Selector switch to DE-FUZE.
- (f) Fit modified E.R.U. cartridge housing with B.N.C. connector, to E.R.U. connector on top of mainplane.
- (g) Press "Clear Wing" push switch and check 28V at B.N.C. connector of modified E.R.U.
- (h) Remove fuse B.J.2 (No.25) from supply panel in underside of fuselage.
- (j) Press "Clear Wing" push switch and check NO VOLTS at B.N.C. connector of modified E.R.U.
- (k) Repeat items f-j on E.R.U. fitted to other mainplane. Return all switches to "OFF" position.

2. R.F. Checks

(a) State 1

- (i) Ensure fuse B.J.2 (N .25) is removed from supply panel.
- (ii) Connect Box R.A.E. No.2 to E.R.U. connector on top of mainplane.
- (iii) Disconnect aircraft supplies plocket on side of pylon.
- (iv) Operate transmitters at selected frequencies and record readings at each frequency. (Upper and Lower aerials where applicable).

(b) State 2

- (i) Reconnect aircraft supplies plocket on side of pylon.
- (ii) Operate transmitters at selected frequencies and record readings at each frequency. (Upper and Lower aerials where applicable).
- (iii) Repeat items 2(a) to 2(b) on pylon fitted to other mainplane.
- (iv) Switch off and disconnect ground power supplies.

/3. ...

3. Surge (Engine Running)

- (a) Ensure fuse B.J.2 (No.25) is removed from supply panel.
- (b) Ensure aircraft supply plocket is fitted to E.R.U. plocket on side of pylon.
- (c) Connect box S.8A to B.N.C. connector on modified E.R.U. (which is connected to A/C supplies).
- (d) Start engine. Switch "ON" and "OFF" all equipment listed in Appendix D.
- (e) Read out and record.
- (f) Disconnect box S.8A and modified E.R.U.
- (g) Connect modified E.R.U. and box S.8A to pylon on other mainplane.
- (h) Switch "ON" and "OFF" all equipment listed in Appendix D.
- (j) Read out and record.
- (k) Switch off engine and replace fuse B.J.2 (No.25) at end of trial.

Appendix B to Arm. 87/11 dated 2nd January. 1963

Hunter G.A. Mk.11

Tests to Ascertain Electro-Magnetic Hazard Compatibility with Aircraft Weapons System

2" Rocket Battery, Launcher No.3, Mk.1

1. Aircraft Circuit Checks

- (a) Ensure that all explosives have been removed from the aircraft and an entry made in F.700.
- (b) Connect and switch "ON" ground power supplies.
- (c) Fit Armament Safety Plug to the socket in the underside of the port mainplane.
- (d) Fit the modified 24 way firing bar to the rear of the rocket launcher.
- (e) Fit the modified ripple unit into the launcher.
- (f) Switch the "Butt Test" switch to "ON".
- (g) Select RIPPLE/NORMAL switch to RIPPLE.
- (h) Select BOMBS/R.P. switch to R.P.
- (j) Raise safety catch on top of control column and press R.P. firing button.
- (k) Check for 28V at B.N.C. connectors fitted to modified firing bar.
- (1) Trip circuit breaker No.2 on supply panel in underside of fuselage.
- (m) Raise safety catch on top of control column and press R.P. firing button.
- (n) Check NO VOLTS at B.N.C. connectors fitted to modified firing bar.
- (o) Repeat on launcher fitted to other mainplane.
- (p) Return all switches to "OFF" position.

2. R.F. Checks

(a) <u>State 1</u>

- (i) Ensure circuit breaker No.2 is tripped.
- (ii) Remove modified ripple unit from launcher.
- (iii) Connect R.F. box B.D./1 to B.N.C. connectors on modified firing bar.
- (iv) Using upper and lower aerials where applicable, operate transmitters at selected frequencies and record at each frequency.

(b) State 2

- (i) Fit modified ripple unit into the launcher.
- (ii) Using upper and lower aerials where applicable, operate transmitters at selected frequencies and record at each frequency.

/(iii) ...

- 2 **-**

Appendix B Cont'd.

- (iii) Repeat items 2(a) to 2(b) on launcher fitted to other mainplane.
- (iv) Switch "OFF" and disconnect ground power supplies.

3. Surge (Engine Running)

- (a) Ensure circuit breaker No.2 is tripped.
- (b) Ensure modified ripple unit is fitted to launcher.
- (c) Connect Boxes S.8B and S.8C to B.N.C. connectors on modified firing bar.
- (d) Start engine. Switch "ON" and "OFF" all equipment listed in Appendix D.
- (e) Read out and record.
- (f) Repeat on launcher fitted to other mainplane. Switch off engine and re-set circuit breaker No.2 at end of trial.

Appendix C to Arm. 87/11 dated 2nd January, 1963

Hunter G.A. Mk.11

Tests to Ascertain Electro-Magnetic Hazard Compatibility with Aircraft Weapon Systems

3" Rockets

1. Aircraft Circuit Checks

- (a) Ensure that all emplosives have been removed from the aircraft and an entry made in F.700.
- (b) Connect and switch "ON" ground power supplies.
- (c) Fit Armament Safety Plug to the socket in the underside of the port mainplane.
- (d) Select the Fuzing Selector switch to DE-FUZE.
- (e) Place the Butt Test switch to ON.
- (f) Select BOMBS/R.P. switch to R.P.
- (g) Switch the R.P. selector switch to No.8.
- (h) Select the RIPPLE/NORMAL switch to NORMAL.
- (j) Fit 3" rocket leads with B.N.C. connectors as follows:-
 - (i) ROCKET RAIL "A" in BOTTOM PHUG (No.1 Rocket)
 - (ii) ROCKET RAIL "B" in TOP PLUG (No.10 Rocket)
 - (iii) ROCKET RAIL "C" in BOTTOM PLUG (No.3 Rocket)
 - (iv) ROCKET RAIL "D" in TOP PLUG (No.12 Rocket)



Appendix C Cont'd.

- (k) Press the R.P. reset button (in mains supply hatch) and ensure "Dolls Eye" shows up.
- (1) Raise safety catch on top of control column and press R.P. firing button.
- (m) Check 28V on B.N.C. connectors on flying leads of TOP plugs.
- (n) Press R.P. firing button TVICE more and third press will give 28V on B.N.C. connectors on flying leads of BOTTOM plugs.
- (o) Trip circuit breaker No.2 and re-set "Dolls Eye" by pressing R.P. re-set button.
- (p) Raise safety catch on top of control column and press R.P. firing button.
- (q) Check NO VOLTS on B.N.C. connectors on flying leads of TOP plugs.
- (r) Press R.P. firing button twice more and check NO VOLTS on BOTTON plugs.
- (s) Repeat on rocket rails of other mainplane.
- (t) Return all switches to "OFF" position.

R.F. Checks

- (a) Ensure circuit breaker No.2 is tripped.
- (b) Connect R.F./BD/1 as follows:-

 - (ii)
 - Channel 1 Rocket rail 'A' (Bottom plug)
 Channel 2 Rocket rail 'B' (Top plug)
 Channel 3 Rocket rail 'C' (Bottom plug) (iii)
 - Channel 4 Rocket rail 'D' (Top plug) (iv)
- (c) Using upper and lower aerials where applicable, operate transmitters at selected frequencies and record at each frequency.
- (d) Repeat on rocket rails fitted to other mainplane.

Surge (Engine Running)

- (a) Ensure circuit breaker No.2 is tripped.
- (b) Connect S.8 boxes as follows: -

 - (i) S.8A Rocket rail 'A' (Bottom plug)
 (ii) S.8B Rocket rail 'B' (Top plug)
 (iii) S.8C Rocket rail 'C' (Bottom plug)
 (iv) S.8F Rocket rail 'D' (Top plug).
- (c) Start Engine. Switch "ON" and "OFF" all equipment listed in Appendix D.
- (d) Read out and record.
- (e) Repeat on rocket rails fitted to other mainplane.
- (f) Switch off engine and reset circuit breaker No.2 at end of trial.

Appendix D to Arm. 87/11 dated 2nd January, 1963

Hunter G.A. Mk.11

Airborne Radio Installations and Electrically Operated Services

- 1. Airborne Radio Installations
 - (a) A.R.I. 18124 U.H.F.
 - (b) A.R.I. 5848 I.F.F. Mk.10.
- 2. Electrically Operated Services
 - (a) Fire Warning (Test push only).
 - (b) Engine Anti-Icing.
 - (c) Emergency fuel pump.
 - (d) Tailplane, rudder and aileron trim control.
 - (e) Elevator and aileron power control.
 - (f) Tailplane control and "standby" control.
 - (g) Flap control.
 - (h) Hood control.
 - (j) Cabin pressurisation and temperature control and test switch.
 - (k) Airbrake test switch.
 - (1) Cabin and navigation lights.
 - (m) Pitot head heater.
 - (n) G.G.S. retractable mounting.

Appendix E to Arm. 87/11 dated 2nd January, 1963

Hunter G.A. Mk.11 WT.810

Modification State

Modifications:

7, 13, 15, 17, 18, 22, 23, 24, 25, 27, 28, 29, 30, 31, 32, 33, 35, 36, 37, 38, 40, 41, 43, 44, 45, 46, 47, 48, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 63, 65, 66, 67, 68, 69, 70, 72, 75, 76, 77, 78, 79, 80, 82, 83, 84, 85, 86, 87, 89, 90, 94, 98, 99, 101, 102, 103, 104, 106, 107, 108, 109, 110, 111, 113, 114, 115, 116, 117, 123, 125, 126, 130, 131, 132, 133, 135, 136, 138 B, 139, 141, 142, 143, 147, 150, 151, 152, 153, 158, 159, 160, 168, 169, 173, 175, 179, 180, 182, 183, 185, 187, 188, 192, 193, 194, 195, 196, 201, 203, 205, 208, 209, 210, 213, 216, 221, 223, 225, 227, 228, 229, 233, 248, 249, 251, 252 Part, 256, 258, 262, 265, 266, 268, 273, 274, 278, 283, 290, 291, 294, 295, 297, 303 Part, 305, 306, 307, 312, 314, 317 B, 318, 319, 321, 322, 324, 325, 327, 328, 329, 330, 331, 332, 344, 345, 346, 347, 349, 352, 354, 356, 357, 360, 363, 365, 369, 374 B, . 377, 386 A, 390, 392, 396, 398, 402, 403, 404, 406, 413, 416, 427, 428, 436, 437, 444, 446, 449, 450, 451, 452, 453, 457, 462, 465, 467, 468, 473, 478 B, 481, 486, 487, 488, 490, 497, 498, 499, 502, 510, 518, 522, 533, 536, 543, 546, 549, 550, 554 B, 557, 564, 566, 567, 568, 569, 572 B, C & E, 578, 580, 581, 586, 591, 597, 602, 604, 605, 615, 616 Part, 617, 621, 629, 644, 656, 657, 677, 678, 682, 690 A & C, 692, 696, 697, 705, 723, 725 A, 753, 766, 768, 775, 776, 777, 781, 811, 812, 827, 834, 841, 846, 895, 903, 907, 912, 919, 922, 932, 933, 937, 943, 948, 950, 956, 961, 964, 967, 988, 990, 991, 996, 1000, 1001, 1004, 1007, 1014, 1025, 1040, 1045, 1056, 1065, 1076, 1082, 1083, 1084, 1088, 1091, 1112 Trial Installation, 1123.

Ejection Seat:

Nain Gun Ser. No. 2569 Mods. 843, 219. Seat Comp. Ser. No. 2 Mods. 2378, 2377. Drogue Gun Ser. No. 6734 Mods. 226, 227, 244, 384, 465, 513, 831.

<u>S.T.I.'</u>s

Hunter - 5, 6, 7, 9, 10, 15, 17, 18, 19, 21, 25, 30, 31 A, 32, 34, 35, 38, 39, 41, 42, 43, 48, 51 A, 54, 57, 60, 61, 64 A, 67, 69, 71, 74, 75, 81, 82, 85, 91 A, 93 B, 94, 97, 98, 100, 103, 105, 107, 109, 115, 117 A, 118, 119, 120, 126, 127, 128, 132, 136, 138, 440 A, 142, 143, 148, 153, 166, 168, 173, 175, 181, 182 A, 186, 196, 199, 202, 203, 207 A, 214, 215, 225, 227, 228, 237, 241, 238, 242 B Part 1, 246, 248, 250, 235 B.

Blectrical = 101, 102, 103, 106 A, 103 A, 112, 113, 115 A, 117 B, 119 C, 126 A, 131 A, 135, 180 A, 198, 199, 200, 181, 186.

Instruments - 60 A, 71, 76, 78 A, 83 B, 85 A, 94, 95, 80, 116. Misc. - 227, 230, 235 B, 238, 257.

/Radio ...

SECRE

Radio, Airborne - 162, 166. Safety Equip. - 73.

S.T.N.'s

Electrical - 47, 73, 83, 86. Instruments - 72, 86. Hunter - 46.

8.I. 's

Hunter - 11 A, 15, 28 A, 48 A, 64 A, 72 B, 63, 78, 7, 68 A.

Inst. - 19, 15, 20 A, 13, 11, 12 A, 14 A.

Electrical - 30 C.

Safety Equip. - 4.

N.A.M.O.'s

Gen/1056, Gen/X126, Gen/P98.

Modifications

Basic Engine - 259, 264, 270, 287, 295, 298, 355, 376, 406 Pt. 2, 407, 448, 470, 506, 511 Pt. 1 and 2, 525, 528 Pt. 2, 541, 591, 593, 596, 610, 612, 614, 640, 648, 683 Pt. 3, 763, 765, 776 Pt. 2, 796, 814 Pt. 3 & 4, 826, 827 Pt. 2, 823, 830 Pt. 6, 836, 838, 839, 844, 869 Pt. 2, 882, 896, 905 Pt.1, 908, 909, 921, 923, 924, 926, 1009, 1013, 1025, 1026, 1038, 1091, 1094, 1096, 1106, 1134 Pt. 2, 1188, 1198, 1206, 5013, 5016 Pt. 2, 5017 Pt. 2, 5018, 5026 Pt.2, 5027, 5030 Pt. 2, 5032, 5033, 5034, 5044, 5052 Pt.2, 5054 Pt. 3, 5059 Pt. 2, 5063, 5066 Pt. 2, 5067, 5077 Pt. 2, 5107 Pt. 2, 5109, 5113, 5127, 5130, 5131, 5138 Pt. 2, 5153, 5155, 5157, 5160 Pt. 2, 5175, 5180, 5184, 5190 Pt. 2, 5209 Pt. 1, 5213, 5233, 5255, 5265, 5274, 5276, 5277, 5270, 5287 Pt. 1, 2, 3 & 4, 5291, 5300, 5301, 5302, 5303 Pt. 2, 5305, 5310, 5315, 5318, 5319, 5320 Pt. 2, 5326, 5327, 5333, 5336 - Pawl Racket 1 Off, 5348, 5349, 5357, 5367, 5374, 5380 Pt. 1 & 3. Installation Fittings - 486, 781.

S.T.I.'s

Avon - 16A, 31.

S.T.N.'s

Misc. 102.

S.I.'s

Avon 17 A.

Hunter - 14 A, 15, 28 A, 30 C, 32 A, 41, 46, 47, 48 A, 60, 61, 62, 63, 64, 65 A, 68, 70 B, 72 B, 73.

Electrical - 13, 12 B, 30.

Modifications

Drop Tanks, Bristol - 1, 2, 3, 4, 5, 11, 33. Hunter - 555, 883, 976.

Appendix F to Arm. 87/11 dated 2nd January, 1963

RESULTS

R.F. and Surge

E.R.U. Jettison - Hunter G.A. Mk.11 WT.810

Date of Trial: 9th October, 1962

R.F.

Equipment	Frequency		Chan				
Eduthwette	rrequency		2	2	2	2	
		State	2(a	.)	2(1)	
1		Station	St	Pt	St	Pt	
U.H.F.	225 250 275 300 305•5 310 311 312 313 314 315 316 317 318 319 320 325 350 375 399•9		NI NI NI 8 . 54 T NO T NO T 1 . 4 . 12 NI	est est NT est est est	NI 8 465 2 6666 5 7 48 5 7 48 5 7 48 11 11 NI		milliwatts "" "" "" "" "" "" "" "" "" "" "" "" ""
U.H.F. Standby	243.8		NI	NI	NI	NI	II
I.F.F. Mk. 10	All Modes		NI	NI	NI	NI	u

SURGE

Channel	A/C Test	Port	Stbd.	
Neg. Pos. Energy	3 "	.8 volts 1.2 volts 0	.8 volts .8 volts 0) for less than .5 μ second

RESULTS

R.F. and Surge

2" R.P. - Hunter G.A. Mk.11 WT.810

Date of Trial: 10th October, 1962

R.F.

Equipment	Frequency	A/C Test						
rdarbinetto.	rrequency	A) C lest		1	2	1	2	
			Rocket Station	Stb	•	Por	t	
			Rocket Post	Centre	Lower L/H	Centre	Lower I/H	
U.H.F.	225 250 275 300 325 350 375 399•9	2(a) "" "" "" "" "" "" ""		1.05 .4 .21 .15 NI NI NI .08	.59 .58 .9 .1 .1 NI NI	.75 .3 .21 .15 NI NI NI NI	.1 .5 .1 NI NI NI NI	milliwatts " " " " " " "
U.H.F. St by	243.8	19		NI	NI	NI	NI	11
I.F.F. Mk.10	All Modes	n .		NI	NI	III	ИІ	tt
U.H.F.	225 250 275 300 325 350 375 379•9	2(b) " " " " " "		.3 NI .22 .22 MI MI NI NI	•5 •4 •1 •1 •1 •1 •1 •1	.75 .39 NI .08 .08 .08 NI NI	NI •5 NI NI •1 NI NI	60 90 90 91 17 91
U.H.F. St By	243.8	"		MI	NI	NI	NI	"
I.F.F. Mk.10	All Modes	н		М	NI	NI	NI	"

SURGE

Channel	A√C Test	Stb	•	Fort				
		Centre	Lower	Centre	Lower			
Energy	3	0	0	Ç	0	microjoules		

SECRET

Appendix H to Arm. 87/11 dated 2nd January. 1963

RESULTS

R.F. and Surge

3" R.P. - Hunter G.A. Mk.11 VT.810

Date of Trial: 9th October, 1962

R.F.

7	7	A/C Test			Channel							
Equipment	Frequency			1	2	3	4	1	2	3	4	
			Main Plane									
			Rail No.	A/b	B/t	С/Ъ	D/t	A/b	B/t	с/ъ	D/t	(b=bottom t=top)
U.H.P.	225 250 270 275 280 285 290 295 300 305 325 350 375 399•9	2 11 11 11 11 11 11 11 11 11 11 11		No No .05 No	NI NI Test Test	.13 .13 .1 .1 .1 .1	.18 .55 1.35 .9 .35 .1 .13 .25 .13 NI	.1 .15	No No No No .14 No	NI NI Test Test Test Test NI NI NI	•09	milliwatts " " " " " " " " " " " " " " " " " "
U.H.F. St by	243.8	"				No	Indi	cati	on I			ţ1
I.F.F. Mk.10	All Modes	"				No	Indi	cati	on i			"

SURGE

A/C Test			Stbd.				Po			
	Channel	A/b	B/t	ር/ኑ	D/t	A/ b	B/t	C/Ъ	D/t	
3	Energy µj	0	2.5 15	0	0	0	0	0	0	microjoules



Information Conve-Knowledge Services (dstl) Porton Down, Salishary Wars 8P4-079 22000-0278 Let - 0.1980-613753 Fee 11280-613770

Defense Technical Information Center (DTIC) 8725 John J. Kingman Road, Suit 0944 Fort Belvoir, VA 22060-6218 U.S.A.

AD#: AD343602

Date of Search: 20 May 2009

Record Summary: AVIA 18/4397

Title: Hunter G.A. MK.11 WT. 810 Clearance Trials of 25 lb. Practice Bombing Installation Availability Open Document, Open Description, Normal Closure before FOI Act: 30 years

Former reference (Department), 890/10 Pt 1 Held by: The National Archives, Kew

This document is now available at the National Archives, Kew, Surrey, United Kingdom.

DTIC has checked the National Archives Catalogue website (http://www.nationalarchives.gov.uk) and found the document is available and releasable to the public.

Access to UK public records is governed by statute, namely the Public Records Act, 1958, and the Public Records Act, 1967.

The document has been released under the 30 year rule.

(The vast majority of records selected for permanent preservation are made available to the public when they are 30 years old. This is commonly referred to as the 30 year rule and was established by the Public Records Act of 1967).

This document may be treated as <u>UNLIMITED</u>.